ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0181, W0194, W0183, W0150, W0179, W0190, W0175, W	Vinayaka Lyt 3rd Crs, NA	Vikas layout and Maruthinagara
Segment No.	**Total Length (m)**	
1/C-W0181/S122323	666.01	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	59.51	77.605209	13.109180	77.605357	13.108832	WO 147	WO 150
2	48.18	77.604847	13.109429	77.604740	13.109006	WO 166	END
3	66.84	77.606475	13.108897	77.607073	13.108747	WO 164	END
4	144.85	77.608533	13.109792	77.609850	13.109772	WO 150	END
5	145.47	77.608620	13.108167	77.609953	13.108311	WO 180	END
6	61.24	77.607363	13.107525	77.607925	13.107579	WO 190	END
7	69.94	77.607358	13.107271	77.608002	13.107311	WO 194	END
8	69.98	77.607399	13.106704	77.608042	13.106748	WO 206	END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to roads and drains at Vikas layout and Maruthinagara and surrounding areas in ward No:01 of Yelahanka Sub Division	10000000	2017-18
Year	**Type of Work**	**Other Work Type**
2017 - 2018	Others	
Tender	**Work Details**	**Job No. / Work Code**
Not a Tender	Improvements to roads and drains at Vikas layout and Maruthinagara and surrounding areas in ward No:01 of Yelahanka Sub Division	001-18-000023
Work Order No.	**Work Order Date**	**Period of Extention**
Work order No :BBMP/EE/YNK-D/WO/115/2017-18	25/02/2018	NOT TAKEN
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**

2018	24/02/2019	No

ntractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
KRIDL, BANGALURU		0.00
Phone No.	**E-Mail ID**	
9035609668		

Zone: YELAHANKA **Ward No:** 1 **Ward Name:** Kempegowda Ward **Street ID:** W0181, W0194, W0183, W0150,

Inspection Details

Number of Trees	Any Other Information	Name
		sachin
Date of Inspection	**Remarks**	
24/04/2018		

Category	Image	Photo Remark
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.
Segment Start		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0181, W0194, W0183, W0150,